

HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS

HAER
MINN
27-MINAP,
20A-

WASHBURN CROSBY MILLING COMPLEX,
WASHBURN "A" MILL
710 - 714 South 2nd Street
Minneapolis
Hennepin County
Minnesota

HAER NO. MN-83-A

Jet Lowe, Photographer, November 1993

- MN-83-A-1 BIRD'S EYE VIEW OF FIRE DAMAGE.
- MN-83-A-2 INTERIOR VIEW OF NORTHEAST WALL LOOKING NORTHEAST AT FIRE DAMAGE.
- MN-83-A-3 INTERIOR VIEW OF NORTH WALL LOOKING NORTH AT FIRE DAMAGE.
- MN-83-A-4 INTERIOR VIEW OF EAST WALL LOOKING EAST AT FIRE DAMAGE.
- MN-83-A-5 INTERIOR VIEW OF NORTHWEST WALL LOOKING NORTHWEST AT FIRE DAMAGE.
- MN-83-A-6 INTERIOR VIEW OF SOUTHWEST WALL LOOKING AT FIRE DAMAGE.
- MN-83-A-7 INTERIOR VIEW OF SOUTHWEST WALL LOOKING SOUTHWEST AT FIRE DAMAGE.
- MN-83-A-8 INTERIOR VIEW OF EAST WALL LOOKING EAST AT FIRE DAMAGE.
- MN-83-A-9 INTERIOR VIEW OF EAST WALL LOOKING EAST AT FIRE DAMAGE.
- MN-83-A-10 INTERIOR VIEW OF NORTH WALL LOOKING NORTH AT FIRE DAMAGE.
- MN-83-A-11 INTERIOR VIEW OF SOUTHWEST LOOKING EAST AT FIRE DAMAGE.
- MN-83-A-12 PHOTOGRAMMETRIC IMAGE OF NORTHWEST FACADE LOOKING SOUTHEAST AT FIRE DAMAGE.

WASHBURN CROSBY MILLING COMPLEX,
WASHBURN "A" MILL
HAER NO. MN-83-A
(PAGE 2)

- MN-83-A-13 PHOTOGRAMMETRIC IMAGE OF NORTH FACADE LOOKING SOUTH
AT FIRE DAMAGE.
- MN-83-A-14 PHOTOGRAMMETRIC IMAGE OF NORTHWEST FACADE LOOKING
SOUTHEAST AT FIRE DAMAGE.
- MN-83-A-15 PHOTOGRAMMETRIC IMAGE OF NORTHWEST FACADE LOOKING
SOUTHEAST AT FIRE DAMAGE.
- MN-83-A-16 PHOTOGRAMMETRIC IMAGE OF NORTH FACADE LOOKING SOUTH
AT DETAILS OF WINDOWS.
- MN-83-A-17 PHOTOGRAMMETRIC IMAGE OF SOUTH FACADE LOOKING NORTH
AT FIRE DAMAGE.
- MN-83-A-18 PHOTOGRAMMETRIC IMAGE OF NORTHEAST FACADE LOOKING
SOUTHWEST